

FIG. 1







FIG. 2





Retardation of LC and compensator plate (nm)






F1G. 7







Retardation (nm) of LC







FIG.11


Retardation of LC + quarter wave plate(nm)





FIGI2
















linear SOP, 0°

II, III, IV



linear SOP, 45° linear SOP, -45°

FIG, 19

v



circular SOP, - circular SOP, +

VI



linear SOP, 75° linear SOP, -15°




Fig. 20





Fig. 21



F10,22




FIG. 23

Retardation of LC + quarter wave plate(nm)




FIG. 24